

DIY Astronomy

Telescope Mount Improvements


Doug Holland

In the world of astrophotography, there are a lot of things that can go wrong.

Luckily, everything we need to know is documented in the handbook: 'Basics of Astrophotography' =>



BASICS OF ASTROPHOTOGRAPHY



VOLUME ONE

Telescope Mount - One of the most important components in astrophotography.

For average focal length telescope and average pixel pitch camera:

1 pixel correlates to about 1 arc second in sky

1 degree = 60 arc minutes

1 arc minute = 60 arc seconds

⇒ 1 degree = 60 x 60 = 3600 arc seconds

- Challenging to get mechanical system to track the sky within 1 arc second
 - Otherwise, smeared pixels / image



Mount to be improved: Losmandy G11

=> Principals apply to other mounts too

Declination (DEC) Axis –

North / South

Right Ascension (RA) Axis –

East / West

Issues –

DEC: Stiction (static friction)

=> Jerkiness during movement

RA: Periodic Error

=> Elongated stars, smeared images

RA

DEC



Mount built in 2005, purchased used in 2010.

DEC: Stiction (static friction)
=> Jerkiness during movement



Disassemble

Remove DEC axis

Thrust bearings gummed up with old lubricant – causing stiction



Thrust Bearings

Thrust bearings gummed up with old lubricant – causing stiction



Clean & Degrease
All metal components

Ventilation



Lubricate:

Super Lube (Teflon base) +
Tungsten Disulfide WS2 Powder



Thrust Bearings



Reassemble



Much Improved Stiction

RA: Periodic Error

=> Elongated stars, smeared images

1. First have to understand how RA axis works



RA axis with DEC axis removed


Oldham Coupler
Couples Gear Box
to Worm Gear

Gear Box

Motor

Ring Gear

Worm Gear



Periodic Error – Changes in rate of RA axis rotation due to imperfections in Worm Gear & associated mechanism. Repeats once per rotation of Worm Gear (e.g. 4 minutes).

Changes Made (cont'd)

1. Disassembled, degreased & lubricated RA axis



Lubricate:

Super Lube (Teflon base) +

Tungsten Disulfide WS2 Powder


Clean & Degrease

All metal components

Changes Made (cont'd)


2. Replaced bearings

- Tried Boca Bearings and Losmandy replacement bearings
- Others prefer Boca, I had better luck with Losmandy





Changes Made

3. Added Belleville Washer to Bearing Block





Applies tension to worm gear / ring gear interface.
Keeps worm gear from moving back & forth.



Changes Made (cont'd)

4. Replaced & applied Super Lube to Oldham Coupler



Changes Made (cont'd)

5. Set gap between Worm Gear & Ring Gear

=> Use gap gauge to set Bearing Blocks

* Reduce backlash

- vs. -


* Being too tight thus stalling motor
(RA Motor Lags message)



Gap Gauge / Feeler Gauge

Right Bearing Block
moves more than left

In end – Worm Gear should
move smoothly, but no play
/ backlash.



Changes Made (cont'd)

6. Aligned motor with Oldham Coupler & Worm Gear to decrease movement of Oldham Coupler during rotation

Motor + Gear Box mount here



File out motor mount holes and fill in. Align with Oldham Coupler.




Changes Made (cont'd)

7. Truth is Truth


- 7.1 Re-did adjustments 4 times before satisfied.
- 7.2 Damaged multiple bearings during process.
- 7.3 Got 'RA Motor Lags' message after initial adjustment.
- 7.4 Started with 2 Belleville Washers, changed to 1.
- 7.5 Had difficulty getting bearings out of bearing block. Had to buy new bearing blocks.
- 7.6 Found that Ring Gear had some 'high spots' where Worm Gear encountered more friction.
- 7.7 Got grease on Clutch Plates. Had to disassemble to clean.

Results (Unguided)

Obtained using PHD2 Guiding Assistant (under Tools)



Before – Approx. 11" peak to peak periodic error.




After – Approx. 4" peak to peak periodic error. (Ignoring drift)


Results (Guided)

Prior to adjustments, typical approx. 1.5" RMS error

{{{ Comparison of ST4 vs. Pulse Guiding }}}



ST4 / Autoguiding Port: 0.58" RMS error



Pulse Guiding / RS232 Port: 0.43" RMS error

Image taken after mods:

1. Smaller stars
2. Stars less elongated

M13 –
Globular Cluster
in Hercules



www.holland-observatory.net

The End